

Document availability: **Public**

## Title: Discontinuation of certain uEye cameras with CMV4000 sensors

<b>Affected Product:</b>	IDS uEye cameras (detailed list of models in document) <ul style="list-style-type: none"> <li>• UI-337xACP (USB3)</li> <li>• UI-337xSE (USB3)</li> <li>• UI-537xCP (GigE)</li> <li>• GV-537xCP (GigE)</li> </ul>
<b>Document Version:</b>	1.1 Invalidates the former version 1.0 of this document from 8 <sup>th</sup> March 2022.
<b>Release date:</b>	October 30 <sup>th</sup> 2023

### Reasons and Description of the Product Discontinuation

The supplier of the imaging sensors built into the affected cameras has decided to strongly increase prices for the imaging sensor CMV4000-3E5C1LP (colour), CMV4000-3E5M1LP (monochrome) and CMV4000-3E12M1LP (NIR). IDS therefore decided to announce the discontinuation of the affected cameras below. IDS' goal is to offer up to date sensors with a good price/performance ratio.

### Recommended action for customers


IDS recommends its customers to check demands and place orders until the last time buy date. For any question regarding last time orders or successor models, please contact our sales team.

### Important Dates

End of Sale	Last Shipment Date	End of Support
30 <sup>th</sup> September 2022	31 <sup>th</sup> December 2022	31 <sup>th</sup> December 2025

### Affected Cameras

Illustrations may differ from the original.




UI-337xACP




UI-5370CP  
GV-5370CP



UI-3370SE



UI-3371SE



UI-3372SE



# Product Discontinuation Notification

## Affected Part Numbers

UI-337xACP cameras			
AB03569			

UI-337xSE cameras			
AB02632	AB02633	AB02634	AB02635
AB03569	AB02630	AB02631	

UI-5370CP cameras			
AB00478	AB00479	AB00481	AB00645
AB00922	AB00923	AB01105	AB01106
AB01107	AB01123	AB01126	AB01338
AB03021	AB03257		

GV-5370CP cameras			
AB02017	AB02018		